



© 1999 Drawings remain the property of Vental Australia Pty. Ltd.



V80 COUPLING DETAIL - PLAN VIEW

Dwg. No. V10401

Manually operated blind with end fitted gearbox showing crank penetration in plan view. Manual crank operated blinds require adequate provision to be made for the internal mounting of the crank head as well as a clear path for the crank penetration - unobstructed by structural steel, lintel bars, etc.