



© 1999 Drawings remain the property of Vental Australia Pty. Ltd.



V80 CRANK DETAIL - SECTION VIEW

Dwg. No. V10102

Manually operated blind with gearbox showing 90 degree crank penetration in section view. Manual crank operated blinds require adequate provision to be made for the internal mounting of the crank head as well as a clear path for the crank penetration - unobstructed by structural steel, lintel bars, etc. The above example shows a concrete lintel/recess (with timber wedge for screw fixing) and false window head to simplify crank fitting.