



© 1999 Drawings remain the property of Vental Australia Pty. Ltd.

**Vental** AUSTRALIA

**V80 HEAD DETAIL - SECTION VIEW**

**Dwg. No. V10101**

Manually operated blind with gearbox showing 90 & 45 degree crank penetrations in section view. Manual crank operated blinds require adequate provision to be made for the internal mounting of the crank head as well as a clear path for the crank penetration - unobstructed by structural steel, lintel bars, etc. The above example shows a blind fitted with a type 100 cover (refer to dwg. no. V20101).